Solar Connection

Connections

Connections for photovoltaic cables



20103 LX-MC4

Cross wrench for installing MC4 fuse holders

Pair of wrenches for the installation of 1500V MC4 fuse holder connectors, MC4 type. Specific tool for assembling and disassembling male/female photovoltaic connectors and fuse holders, as well as for their adjustment.

Code	Ref.	Kg x 100	₽ Bag	Box
385010	LX-MC4	-	-	-