

30902 ECBT-SHUNT3

3 clamps

Earthing and short-circuit kit for low-voltage distribution boards.
The main reason for their installation is to protect the worker from accidental power-on or return of voltage during repair work.
According to IEC 61230 standard.

Low voltage



**SHUNT SHCD
and SHUNT SHPL**
Insulated earth clamps



TT-38A
Earthing lathe

Composed of:

- 3 insulated SHUNT clamps for short circuit of the phases.
- 3 copper PVC-insulated cables 25 mm² section and 0.4 m long for short circuit of phases.
- 1 copper PVC-insulated cables 25 mm² section and 1 m long for earthing.
- 1 branch-joint connector (4 cables).
- 1 TT-38A earthing lathe.
- 1 plastic case for storage and transport.

Code	Ref.		Maximum current of work
659040	ECBT-SHCD3	Bare wire	200 A
659045	ECBT-SHPL3	Platen	